

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

V-6

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.



1/16 Corner common to Sections
29, , , and 32

Corner consists of a (not) in place
State condition

Dimensions above ground inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS


METAL CORNERS



Mound of is located

 Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box
and fill blanks below, giving bearings from Corner to Trees
and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

J. M. Morrison

(Signature)

Sept. 1960

(Date)


Forestry aid

(Title)

Robert E. Jones
Asst. D.F.A.

T. 145 R. 2C S24 Mer.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Baldern tree 8 inches diameter, on the west side of the from which this Corner bears (Bearing) _____ (Distance) _____ Section line marker between Secs. _____ and _____ is on _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) located chains L. W., N., S., from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: Angle of corner

