

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

7-8

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

Corner common to Sections

32, , and

Corner consists of a metal tag (not) in place



State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid of eight boxes for sketching trees and rocks, arranged in two rows of four.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *No answer*

S. M. Morrison

(Signature)

Aug. 1960


(Date)

Forestry aid

(Title)

W. H. Egan
Asst. D.F.R.

T. 145 R. 26 Mer. 52



Metal Location Poster is on a *32* tree *4* inches diameter, on the *North* side of *the* this Corner bears (Bearing) _____ (Distance) _____ Section line marker between Secs. _____ and _____ is on a _____ on the _____ (Tree, post, etc.) _____ located chains *1*, *W*, *N*, *S*, from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Corner* *Blas in hand N. 31 E. of*

