

U. S. Department of Agriculture

FOREST SERVICE

2-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 26 W. Mer.

Sec. Corner common to Sections

32, and 33

Corner consists of a (not) in place

State condition New treated post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? P. S. established

J. S. J. (Signature)

(Signature)

53 (Date)

(Date)

(Title)

Corner again. Set treated post sorbed  
 80 22/33 at point designated by 1951  
 W.O. survey crew. Post is at east edge  
 of small open swamp. PSLP tag placed on  
 7" spruce N. 67 E. 0.20 ch. A 6" balsam  
 is N. 63 W. 0.30 ch. A 7" cedar is  
 S 21 E. 0.06 ch. Corner is 5.15 ch.  
 west of post. of Sec. 7 & 5 of T. 17 N.  
 which is marked by similar post.

Give any further facts which will aid in finding this


chains distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 17 N. R. 26 W. Mer.