

U. S. Department of Agriculture
FOREST SERVICE

A-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

Section Corner common to Sections
4, 5, 32, and 33

Corner consists of a Iron Cap (~~rod~~) in place

State condition good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ Is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Cedar Cedar Cedar Cedar

Diameter 7 9 9 8

Bearing S 38° W S 80° E N 20° E N 73° W

Distance 2.3 links 13 links 45 links 25 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

M. K. Yantzen

(Signature)

8/26/59

(Date)

Dist Ranger

(Title)

Corner again.

Give any further facts which will aid in finding this

~~corner~~ distant.

from which this Corner bears

4 feet NE

side of


tree

tree 8 inches diameter, on the

East side

Metal Location Poster is on a

cedar



(Make sketch of topography near Corner)

Mer.

524

R. 26

T. 14E

33

37