

U. S. Department of Agriculture  
FOREST SERVICE

D-11

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *26* *5th* Mer.

*1/4*

Corner common to Sections

, and *4*

Corner consists of a *yellow tag* (~~stone~~) in place

State condition *good*

Dimensions above ground *54* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *No evidence found*

*M. J. Switzer*

(Signature)

*Asst Ranger*

(Title)


*8/26/59*  
(Date)

Corner again.

Give any further facts which will aid in finding this

~~corner~~ distant.

from which this Corner bears *12 feet SW*  
side of *Tree*  
*25* inches diameter, on the *N.W. 1/4*  
Metal Location Poster is on a *Dark Pine*



(Make sketch of topography near Corner)

T. 14s R. 26 Mer. 5TL