

U. S. Department of Agriculture
FOREST SERVICE

B-12

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *26* *5th* Mer.

1/16 Corner common to Sections
4, _____, and _____

Corner consists of a *yellow tag* (~~not~~) in place
State condition *good*

Dimensions above ground *54* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *No evidence found*

M. F. Lauritzen

(Signature)

Forest Ranger

(Title)


8/13/59
(Date)

Section 26
T. 14 E
R. 26
Mer. 50

Corner again.
see Jones line running E-W

Give any further facts which will aid in finding this
corner distant.

from which this Corner bears
SW - 5/4.
side of tree 9 inches diameter, on the south
Metal Location Poster is on a
tree



(Make sketch of topography near Corner)