

U. S. Department of Agriculture  
FOREST SERVICE

2-18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
35, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (material) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence


S. M. Morrison  
(Signature)

Forestry aid  
(Title)

Aug. 1960  
(Date)

T. 145 R. 26 S. 2 Mer.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Red Pine

tree 12 inches diameter, on the South

side of Tree

from which this Corner bears N. 80° E. 24.00 chains

Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_ is on

a \_\_\_\_\_ on the \_\_\_\_\_

located \_\_\_\_\_ chains E., W., N., S., from Sec. Cor.; 1/2 Cor.; 1/4 Cor.; Witness Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

Blue Pine fence N. 80° E. corner - by a ~~red pine~~ Red Pine yard.