

U. S. Department of Agriculture

FOREST SERVICE

R-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 Mer.

Corner common to Sections 23, 24, 25, and 26

Corner consists of a scribble post (not) in place State condition poor - Down

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Cardinal position diagram with four empty boxes for N, W, S, E.

N W S E

Diagonal position diagram with four empty boxes for NW, SW, SE, NE.

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Two rows of four empty boxes for sketching bearing trees.

Species N.T. Oak } looks like grown over B.T. Diameter 12" } Bearing NE } Distance 3/4 ch } Did not chip it out

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No - looks like re established corner.

R.H. Chas. L. ...

(Signature)

9-22-10


(Date)

D. F. ...

(Title)

Corner again.
 Scribble post 5" square
 on ground about 2 or 3 ft
 North of intersection of
 fence lines.
 On edge of meadow.

Metal Location Poster is on a *Maple*
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)