

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST L-2

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5 Mer.

16 Corner common to Sections 16, 17, 18, and 19

Corner consists of a Alm FSLP (not) in place State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence


[Handwritten Signature]

(Signature)
Forester
(Title)

3/23/61
(Date)

Corner again. Blk. 115. Painted East and North of corner.

Metal Location Poster is on a Burr Oak tree 5 inches diameter, on the East side of the From which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 145 R. 27 Mer. 5