

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

2-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 27W 5th Mer.
Section

Corner common to Sections

31, and 32

Corner consists of a brass capped pipe (not) in place


State condition Good

Dimensions above ground level with ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 31
T 145
R 27

S. 32
T 145
R 27

B. T.

B. T.

Species Tam. Tam.

Diameter 8" 10"

Bearing N18°W N72°E

Distance 80 lks. 101 lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Clifford Smith
CLIFFORD SMITH

(Signature)
Chief of Party

2/3/41


(Date)

(Title)

Blank lined area for notes at the top of the page.

Corner again. Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of tree inches diameter, on the Metal Location Post on a Jack Pine



(Make sketch of topography near Corner)