

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

C-6

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5th Mer.

1/16 Corner common to Sections

5, _____, and _____

Corner consists of a metallog (cast) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

J. M. Morrison

(Signature)


Forester and

(Title)

Aug. 1950
(Date)

T. 145 R. 27 S. 2 Mer.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Birch tree 7 inches diameter, on the north side of line from which this Corner bears (Bearing) _____ and (Distance) _____ is on Section line marker between Secs. _____ and _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) _____ located chains L, W, N, R, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again:

Bliss Jones former N. 1/4 of
corner - corner on top of
line 120 ft.