

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

2-7

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer.

Corner common to Section 32, and

Corner consists of a *Iron* (not) ~~is~~ place

State condition *rotten*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>N</i>			
<i>W</i>			
<i>S</i>			
<i>E</i>			

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>N</i>			
<i>W</i>			
<i>S</i>			
<i>E</i>			

Species *B.P.*

Diameter *7*

Bearing *S74W*

Distance *29*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

F. J. ...
(Signature)

(Date)

(Title)

CORNER IS ON A GOOD
 PLAZED LINE
 RUNNING E-W
 SET FACE ON BIRCH
 8" N8E 44
 FACING COR.

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears
 side of Tree
 tree 7 inches diameter, on the EAST
 Metal Location Poster is on a T.P.

(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

2-7


Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.
South. 1/4 Corner common to Sections
x, x, x, and 32

Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.
 CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

F.S.L.P. 45			
B.T.			

Species J.P.

Diameter 2"

Bearing South from My cor.

Distance 29 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. M. Kandy
 (Signature)

Chief of party
 (Title)

(Date)

Corner again.

Give any further facts which will aid in finding this


29 lks. chains distant.

from which this Corner bears North

side of tree

tree 7 inches diameter, on the N.E.

Metal Location Poster is on a J. Pine



(Make sketch of topography near Corner)

T. 145 R. 97 Mer. 5th

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. T45 N R. R27 W 5th Mer.

1/4 Corner common to Sections

32, and

Corner consists of a brass capped pipe in place



State condition good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S. 71 1/2
32 R27

B.T.

Species N Pine

Diameter 10 in

Bearing N 8° E

Distance 30 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

3/10/01 (Date)

_____ (Signature)

_____ (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


#17

from which this Corner bears N 10° E

side of ^{Tree}

tree 6 inches diameter, on the ^{South end}

Metal Location Poster is on a Jack Pine



(Make sketch of topography near Corner)

T. J. S. N. R. 27 W. S. 2. Mer.