

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

Posted  
9-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. E7 N. Mer.



1/4 Corner common to Sections  
29, 28, and \_\_\_\_\_

Corner consists of a Squared Stake (not) in place  
State condition Rotten

Dimensions above ground 18x2" inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? It appears to be, but has no marking

A. E. Johnson  
Signature.

10-429  
Date.

Estimator  
Title.

Corner again.

Placed in a heavy  
press of paper

Give any further facts which will aid in finding this

~~16 in. dia.~~

from which this Corner bears S 55° W

side of

tree 3. inches diameter, on the

Metal Location Poster is on a *Corner*

		Sec.	Sec.
		Sec. 9	Sec. 9