

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

P  
 P-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N. R. 27W 5th P. Mer.

Quarter Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 20, and 21


Corner consists of an Oak Post (not) in place  
 State condition Good

Dimensions above ground 48 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine Stp. N. Pine Stp. J. Pine

Diameter 10" 10" 5"

Bearing N80°E. S. 45°W. N55°E.

Distance 8 14 61

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

J. A. Gjelhaug  
 (Signature)

Jr. Civil Eng.  
 (Title)

4/23/37  
 (Date)

Corner again: Give any further facts which will aid in finding this


0.03 chains distant.

from which this Corner bears South

side of tree

tree 2 1/2 inches diameter, on the South

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

T. 145N. R. 27W. 5th P. Mer.