

U. S. Department of Agriculture  
FOREST SERVICE

B-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Sec R Mer.

114 Corner common to Sections  
4, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a yellow tag (not) in place

State condition good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence found

Merwin K. Hamilton  
(Signature)

Head Dist. for Range  
(Title)

1/16/59  
(Date)

Faint, illegible text at the top of the page, possibly bleed-through from the reverse side.


*Corner again. See points in the plan.*

Give any further facts which will aid in finding this chains distant.

from which this Corner bears *56.5 SE 7*

side of tree 8" inches diameter, on the *SW*

Metal Location Poster is on a *Spoke Pine*



(Make sketch of topography near Corner)