

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted
E-15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5th Mer.

1/4 Corner common to Sections
3, and 10



Corner consists of a Squared Scribed Stake in place
State condition Rotten Down

Dimensions above ground 2 x 1 1/2 x 40 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? yes
If not, why? _____


Edward J. Merser
Signature.

10-23-29
Date.

Estimator
Title.

T. 145 N. R. 27 W. 5th Mer.

8-3027 (Make sketch of topography near corner.)



Metal Location Poster is on a Tamarack

tree 18 inches diameter, on the south

side of section line

from which this corner bears S 18° W

23 chains distant.

Give any further facts which will aid in finding this

corner again.

Marker on road is 6.14 ch

west of corner