

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

36

123
 4-16
 R

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 27 W 5 th. Mer.

1/16 Corner common to Sections
27, , , and

Corner consists of a 2 sided stake (~~not~~ in place
 State condition Rotted off at ground level

Dimensions above ground 30 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	I/16	1/16	I/16
	S		S
N	W	S	E

NW	SW	SE	NE

Mound of is located

 Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

I/16			
S			
B.T.			

Species Larch

Diameter 8"

Bearing W

Distance 5 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Only 2 sided stake. One B.T.

No F.S.M.

Earl M. Handy
 (Signature)
 Chief of party

6/14/34


(Date)

(Title)

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

Corner is 18.70 chains S. of road stake on Nushka Trail.

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>		<p>Sec.</p>

(Make sketch of topography near Corner)