

U. S. Department of Agriculture

FOREST SERVICE

Posted

A-19

CHIPPEWA

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 27W 5th P/ Mer.

143  
143

$\frac{1}{4}$  Corner common to Sections

35, and 2

Corner consists of a Scribed Stake in place  
State condition

Dimensions above ground 5' x 2 1/2" x 3" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

SW/SE Sec. 35	SE/SW Sec. 35	NE/NW Sec. 2	NW/NE Sec. 2
------------------	------------------	-----------------	-----------------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S	$\frac{1}{4}$ S		
BT	BT		

Species 7S 7S (snag)

Diameter 6" 3"

Bearing S85°W S10°W

Distance .05 ch .12 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_


(Signature)

(Date)

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)