

## U. S. Department of Agriculture

## FOREST SERVICE

Q 21

NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 2 Mer.

1/16 Corner common to Sections

23, , , and 24

Corner consists of a *metal peg* (~~mark~~) in placeState condition *good*

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *no*If not, why? *No evidence of real corner*

\_\_\_\_\_

3/24/59  
(Date)

*J. M. Morrison*  
(Signature)  
*Forestry Aid*  
(Title)

Corner again.  
Blue line from East Face  
to mile - meter log on wall  
near about 12 in. S of corner.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of *the*

tree 6 inches diameter, on the East

Metal Location Poster is on a *Corner*



(Make sketch of topography near Corner)