

U. S. Department of Agriculture
FOREST SERVICE

123

Chippewa

NATIONAL FOREST

8-22

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 87W 5th Mer.

1/16 Corner common to Sections

....., and 1

Corner consists of a Scribed Stake (~~iron~~) in place

State condition Good

Dimensions above ground 2.5 x 2.5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/16</u>			
<u>5</u>			

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No	Bearing	Trees	

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

T. Fairbanks
T. Fairbanks

(Signature)

C. C. Co.


(Title)

6/21/35
(Date)

Metal Location Poster is on a **Balsam** tree ⁶ inches diameter, on the **NE** side of **Corner Stake** from which this Corner bears **N 53° 30' E** chains distant.

Give any further facts which will aid in finding this Corner again.

Blazed Line from North & also from West



(Make sketch of topography near Corner)