

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 28 5th Mer.

1/16 Corner common to Sections
32, _____, and 27

Corner consists of a metal tie (~~not~~) in place



State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence

S. M. Morrison

(Signature)

Forestry Aid

(Title)

11-16-60
(Date)

T. 145

R. 28

5th

Mer.

		Sec 3	
		Sec 9	

Metal Location Poster is on a *Red oak* tree *9* inches diameter, on the *East* side of *the* from which

this Corner bears (Bearing) (Distance) Chains. Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.)

located chains L. W., N., S., from Sec. Cor.; 1/4 Cor.; 1/2 Sec. Cor. (Gross out nonapplicable) Give any further facts needed to find Corner again:

a few days N. 3 S of
Corner - corner has sign on
4 sides.

Chain of 60 ch. W. from

29 28 a good corner. Trace of
32 33 a 6 1/2 ch line