

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 28 5th Mer.

1/4 Corner common to Sections 29, and 32

Corner consists of a metal lg (mm) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

S. M. Morrison

(Signature)


Forestry aid

(Title)

11-16-60

(Date)

T. 145 R. 28 S. 2 Mer.



Metal Location Poster is on a maple tree 4 inches diameter, on the East side of the

from which this Corner bears West, 30 deg, (Bearing) and (Distance) is on Section line marker between Secs. and

is on the (Tree, post, etc.) on the (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; 1/2 Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again: by a corner in side of woods.

Chained 40 chs west from 2928 a good corner 3233