

U. S. Department of Agriculture

FOREST SERVICE

posted

Shippura NATIONAL FOREST

21

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 30+31W 5th P. Mer.

4 Corner common to Sections 31, and 36

Corner consists of a Concrete hub (not) in place State condition Good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

SC T145N R31W R30W S36 S31			
N	W	S	E

NW	SW	SE	NE	

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T145N R30W SC 36

T145N R31W SC 31

L

L

BT

BT

--

--

Species N. Pine J. Pine
 Diameter 14" 6"
 Bearing N5°E N38°W
 Distance 210' 150'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Signature

(Signature)

Dec 22, 1931 (Date)

Estimator (Title)