

U. S. Department of Agriculture

FOREST SERVICE

posted

23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 230 W. S. P. Mer.

1/4 Cor. Corner common to Sections

31, and

Corner consists of a Iron Pipe (not) in place



State condition Good

Dimensions above ground 8 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



SCBT

SCBT



Species N. Oak Aspen

Diameter 7" 12"

Bearing N47°W N90°E

Distance 21' 60'

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Gayle Kyes

(Signature)

Dec 29, 1931

(Date)

Estimator

(Title)