

U. S. Department of Agriculture
FOREST SERVICE

Posted
27

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145N* R. *30W* *5th*. Mer.

Quarter Corner common to Sections

.....,, and *32*.....

Corner consists of a *Br. capped pipe 1"* (nom) in place

State condition *good*.....

Dimensions above ground *2* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>332</i>	<i>1/4</i> <i>332</i>	<i>1/4</i> <i>332</i>	
<i>B.T.</i>	<i>B.T.</i>	<i>B.T.</i>	

diag

Species *W. Pine* *W. Birch* *Aspen*.....

Diameter *30"* *10"* *6"*.....

Bearing *N 59° W* *N 15 1/2° E* *N 77 1/2° W*.....

Distance *35 3/4* *95 1/2* *36 1/4*.....

Do you believe this to be a genuine Land Office Corner? *Yes*.....

If not, why?

Dan B. Rose

(Signature)

7/31/34
(Date)

Compassman
(Title)