

U. S. Department of Agriculture
FOREST SERVICE

Posted

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 30W 5th Mer.

Quarter Corner common to Sections

28, and 29

Corner consists of a Br. Cap Iron ^{1"} (not) in place


State condition good

Dimensions above ground 7" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
529

1/4
528

B.T.

B.T.

Species H. Maple H. Maple

Diameter 6" 4"

Bearing N69°W N77.5°E

Distance 28.5 37.5

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

G. J. Mendenhall

(Signature)

8/28/34
(Date)

Compass Man
(Title)