

U. S. Department of Agriculture

FOREST SERVICE

posted

Chipp. NATIONAL FOREST 211

CORNERS OF THE PUBLIC SURVEY

T. 145 N R. 30 W 5 Mer.

1/4 Corner common to Sections

33, and

Corner consists of a 1/4 Iron Brass Cap (set) in place

State condition Good

Dimensions above ground 6" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Sc			
1/4			
S. 33			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sc			
1/4			
S33			
BT			

Species Maple

Diameter 9"

Bearing N42 1/2 E

Distance 15'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Paul J. [Signature]
(Signature)

Nov 11 - 31

(Date)

Estimator
(Title)

(Title)