

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

*posted R13*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145N* R. *30W* *5<sup>th</sup>* Mer.

*Section* Corner common to Sections

*21, 22, 27, and 28*

Corner consists of a *Not found* (not) in place

State condition

Dimensions above ground  inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of  is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*scribe iron marks show. NR 30W*

*obliterated*

Species *Basswood, R. Basswood*

Diameter *14"* *14"*

Bearing *N60°E* *S85°E*

Distance *30 ft.* *20 ft.*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

*E. J. ...*  
Signature.

*12/23/31*  
Date.

*Chippewa ...*  
Title.