

U. S. Department of Agriculture  
FOREST SERVICE

2-15  
*Filed*  
215

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *195 N* R. *30 W* *5th* Mer.

*Quarter* Corner common to Sections  
*33* and *34*



Corner consists of a *Br. capped pipe* ( ~~mark~~ ) in place  
State condition *good*

Dimensions above ground *?* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>534</i>	<i>1/4</i> <i>534</i>		
<i>B.T.</i>	<i>B.T.</i>		

Species *Aspen W Pine*

Diameter *8"* *30"*

Bearing *N52°34'W* *N69°45'E*

Distance *30 1/2* *31*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*W. B. Rose*

(Signature)

*7/20/34*

(Date)

*Comptroller*

(Title)