

U. S. Department of Agriculture
FOREST SERVICE

Rooted

Chippewa NATIONAL FOREST

217

CORNERS OF THE PUBLIC SURVEY

T. 145 N. R. 30 W. 5th Mer.

Section 12th Corner common to Sections
34, and 35


Corner consists of a Br. Caped Pipe (not) in place
State condition good

Dimensions above ground 1" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of - is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

534	535	535	
-----	-----	-----	--

B.T.	B.T.	B.T.	
------	------	------	--

Species	<u>W. Pine</u>	<u>Dead Birch</u>	<u>Yellow Birch</u>	
Diameter	<u>2 1/2"</u>	<u>12"</u>	<u>14"</u>	
Bearing	<u>N59°W</u>	<u>N61°E</u>	<u>N87°E</u>	
Distance	<u>106 1/4</u>	<u>17</u>	<u>92</u>	

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

A. B. Rose

(Signature)

Comptroller

(Title)

7/27/39
(Date)