

U. S. Department of Agriculture

FOREST SERVICE

posted E17

Chipp NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 30 5 Mer. Sec

Corner common to Sections 3, 2, 10, and 11



Corner consists of a (not) in place State condition

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Table with 2 rows and 4 columns of empty boxes for sketching and recording data.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

Paul Zeluyoff (Signature)

(Signature)

Estimator (Title)

12-29-31


(Date)

(Title)

Intersection of old org. block
 lines, old surveying marks on
 dead pine on which poster
 is located.

Corner again.
 Give any further facts which will aid in finding this
 from which this Corner bears

1/2
 obtains distant.
 side of Sec. 10
 tree 17 inches diameter, on the E
 Metal Location Poster is on a Dead N. Pine



(Make sketch of topography near Corner)