

U. S. Department of Agriculture  
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 22-30 5th Mer.

Meander Corner common to Sections  
7, and 12

Corner consists of a Brass Cap ~~(XXX)~~ in place

State condition Good

Dimensions above ground 14 inches

• Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|   |           |   |          |
|---|-----------|---|----------|
|   |           |   |          |
|   | <u>12</u> |   | <u>7</u> |
| N | W         | S | E        |

|    |    |    |    |
|----|----|----|----|
|    |    |    |    |
|    |    |    |    |
| NW | SW | SE | NE |

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 145N  
R. 20W  
S. 12

T. 145N  
R. 20W  
S. 7

M.C.

M.C.

Species J. Pine J. Pine

Diameter 4.0" 5"

Bearing S. 41° W. S. 28° E.

Distance 45 lks. 97 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Herald Hennes

(Signature)

April 7, 1937

(Date)


(Title)

CORNER OF THE TOWN OF PUTNEY

Corner consists of a ...  
Corner again.  
Give any further facts which will aid in finding this

chain distant  
from which this Corner bears

side of  
tree - 4.5 inches diameter, on the North East  
Metal Location Poster is on a



(Make sketch of topography near Corner)