

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 W. 5 1/2 Mer.

22 Sec. Corner common to Sections
24, and 19



Corner consists of a Metal pipe (not) in place
State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1.45N</u>
<u>20V</u>
<u>1.34</u>

<u>1.45N</u>
<u>23.9V.</u>
<u>1.39</u>

<u>1.3.</u>

<u>1.3.</u>

--

--

Species Ash Ash

Diameter 10" 10"

Bearing N 21 E N 21 E

Distance 41.7 41.5

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Nelson
(Signature)

Dec. 22, 1908