

P-23,24

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 N. R. 30 E. S. 10. Mer.

Corner common to Sections
....., and 24


Corner consists of a Metal Pipe (not) in place
State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION







N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Pin White Birch

Diameter 2" 12"

Bearing 50° E 88° E.

Distance 12.2 Lks. 58.4 Lks.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

Walter Wilson
Dec. 14, 1908 (Signature)

(Date)

(Title)