

U. S. Department of Agriculture
FOREST SERVICE

QR 25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N. R. 30 W 5th Mer.

MC Sec. Corner common to Sections

24, and 19

Corner consists of a Metal Pipe (not) in place

State condition Good

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	24		19

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 145N
R. 30 W
S. 24

T. 145N
R. 29W
S. 19

[Blank box for sketch]

[Blank box for sketch]

B.T.

B.T.

[Blank box for sketch]

[Blank box for sketch]

Species Ash Ash

Diameter 10" 18"

Bearing N21W N3E

Distance 42 lks 42 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Lloyd Folsom

(Signature)

Dec. 11, 1936

(Date)

(Title)