

U. S. Department of Agriculture

FOREST SERVICE

RB

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145N R. 31W 5th Mer.

Section Corner common to Sections

21, 22, 27, and 28

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Marked  
New  
B.T.

Species SPice SPice SPine d.Pine SPine

Diameter 6" 8" 4" 8" 8"

Bearing S. 3/2 E S4W N52W N49 1/2 E S85 E

Distance 196 190 78 370 65 1/2

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

J. A. Gjelhaug

(Signature)

Tech. Eng.

by D. J. Sutton

2-7-35

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *No post*



(Make sketch of topography near Corner)

T. H. SN. R. 31W 5th Mer.