

Form 974-C—Revised May, 1915
 U. S. Department of Agriculture
 FOREST SERVICE

55

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 25 W S. 1/4 Mer.
 Section _____ Corner common to Sections
5, 6, 7, and 8

Corner consists of a 5g Aspen Stake (not) in place
 State condition Set New Stake "Old was Scribbled"

Dimensions above ground 30" - 4" inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	E	

Sec <u>6</u>	Sec <u>7</u>	Sec <u>8</u>	Sec <u>5</u>
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T-146 R-25W S-6	T-146 R-25W S-7	T-146 R-25W S-8	T-146 R-25W S-5
B-T	B-T	B-T	B-T

Species Dead Aspen B-Gilled Fallen Aspen B-Gilled
 Diameter 5" 6" 5" 4"
 Bearing N-42°W S-70°E S-31°E N-64°E
 Distance 75.2Ks 58.4Ks 111.6Ks 77.4Ks

Do you believe this to be a genuine Land Office Corner?
 If not, why?


Merrin Balle
 (Signature)

July 2nd
 (Date) 1936

.....
.....
.....
.....
.....
.....
.....
.....

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)