

U. S. Department of Agriculture

FOREST SERVICE

C5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 25 5th Mer.

Quarter Corner common to Sections 6 and 5

Corner consists of a Wood post (not) in place


State condition Good

Dimensions above ground 4" 4" 30" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT

Species Cedar Cedar stub

Diameter 10 6

Bearing S60W N15E

Distance 1.19 79

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

Leader

11/18/39

(Date)

(Title)

Corner is on edge of drainage ditch

Corner again.

Give any further facts which will aid in finding this


79 lks. chains distant.

from which this Corner bears N15E

side of corner

tree 6 inches diameter, on the North

Metal Location Poster is on a Cedar stub



(Make sketch of topography near Corner)