

Form 574-a Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

T-9

Shippore NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. R. 6W 5th Mer.

1/4

Corner common to Sections

28, and 29

Corner consists of a wood post (see) in place

State condition

Fair

Dimensions above ground 2" x 2" x 1 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/5

B.T.

B.T.

Species J. Pine N.P. 5th

Diameter 12" 20"

Bearing N 1/4 W 54 1/2 E

Distance 64 60

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Walter Hallock

(Signature)


Leader

(Title)

10/25/08
(Date)

UNITED STATES GEOLOGICAL SURVEY
BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C. 20506

Corner again.
Give any further facts which will aid in finding this
chain distant.
from which this Corner bears
side of **CORNER**
tree **1 1/2** inches diameter, on the **N.W.**
Metal Location Poster is on a **N. PINE**



(Make sketch of topography near Corner)