

U. S. Department of Agriculture  
FOREST SERVICE

X-17P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N. R. 36 W. S. 35 Mer.

Corner common to Sections  
35, and 34

Corner consists of a Traverse (not) in place  
State condition Good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>S</u>		<u>S</u>
	<u>35</u>		<u>34</u>


N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

Arthur W. Gager  
(Signature)

9/12/35  
(Date)

Surveyor  
(Title)

Handwritten notes on a grid background, including the number '587' and other illegible scribbles.

Corner again.

Give any further facts which will aid in finding this

chains distant.


From which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

Fence Post



(Make sketch of topography near Corner)

T. 146 N. R. 96 W. S. 24 P. Mer.