

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

✓-8 Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 27 W 5 Mer.

E 1/16 Corner common to Sections
32, 29, and

Corner consists of a scribed stake (not) in place
State condition rotted

Dimensions above ground 2 1/4" x 2 1/4" inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/16</u> <u>S</u>		<u>1/16</u> <u>S</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located ✓

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/16</u> <u>S</u>		<u>1/16</u> <u>S</u>	
<u>B.T.</u>		<u>B.T.</u>	

Species <u>Jack Pine</u>	<u>Jack Pine</u>
Diameter <u>9</u>	<u>8</u>
Bearing <u>N 55° E</u>	<u>S 82° W</u>
Distance <u>2 links</u>	<u>57 links</u>

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

E. N. Juntunen

Signature.


11/19/29
Date.

Estimator
Title.

T. 146 N. R. 27 W. Mer. 5

9-3021

(Make sketch of topography near Corner.)



Metal Location Poster is on a

tree 9 inches diameter, on the E

side of

from which this Corner bears

.02 chains distant.

Give any further facts which will aid in finding this

Corner again.

Good sum along
North line.

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 27 W 5 E Mer.


Section 28, 29, 32, and 33 Corner common to Sections

Corner consists of a Square stake in place
State condition Fair


Dimensions above ground 2 x 2 x 30 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION




DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species NP Stump NP Stump

Diameter 35" 36"

Bearing S43 W S78° E

Distance 55 Lks 51 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Edward Jensen

Signature.

Estimator


11-27-29

Date.

Title.

T. 146 N R. 27 W S. 4 Mer.

8-3021 (Make sketch of topography near corner.)



Metal Location Poster is on a Norway Pine

tree 5 inches diameter, on the

side of

from which this Corner bears N 44° E

.03 chains distant.

Give any further facts which will aid in finding this

Corner again.