

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

V-13 Pites

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 27 W 5 E Mer.

Section 17

Corner common to Sections

27, 28, 33, and 34

Corner consists of a (not) in place



State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 28			
B.T.			

Species 1 Pine Stub

Diameter 12"

Bearing N.W.

Distance

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Edward J. ...

Signature.

11-22-29


Date.

Estimator

Title.

T. 146N R. 27W S. 25 Mer.

8-3027 (Make sketch of topography near Corner.)



Metal Location Poster is on a Norway Pine tree 22 inches diameter, on the south side of SECTION 417E S. E. from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

