

U. S. Department of Agriculture
FOREST SERVICE

P

Chippewa NATIONAL FOREST

V-19

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 27W. 5th Mer.

Quarter Corner common to Sections
26, and 35

Corner consists of a 2" Oak Post (not) in place

State condition Good

Dimensions above ground 40 3/4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N.Pine J.Pine

Diameter 16" 5" 10"

Bearing N28°E. N.10°E.

1/5 Distance 38 12

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug

(Signature)

4/27/37


(Date)

Jr. Civil Eng.

(Title)

Give any further facts which will aid in finding this corner again:

Metal Location Poster is on a *10' dia* tree 5 inches diameter, on the *South* side of *tree* from which this corner bears *S 10° W* chains distant *0.12*



(Make sketch of topography near corner)