

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

X-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEYT. 146 N R. 27 W 5th Mer. $\frac{1}{4}$ Corner common to Sections

35, and 36

Corner consists of a Scribed Squared Stake (not) in place
State condition Good.Dimensions above ground 2" x 3" x 66" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION**DIAGONAL POSITION**

	$\frac{1}{4}$ 5 35		$\frac{1}{4}$ 5 36
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		$\frac{1}{4}$ S	

Species _____ Red Oak. _____Diameter _____ 2" _____Bearing _____ S 78° E. _____Distance _____ 46 Ls _____Do you believe this to be a genuine Land Office Corner? yes


If not, why? _____

Edward Jensen
Signature.

11-16-27
Date.Estimator
Title.

(Make sketch of topography near corner.)

T. 146 N R. 27 W S. 2 Mer.



Metal Location Poster is on a Red Oak

tree 6" inches diameter, on the East

side of Section line

from which this Corner bears N 78° E

.05 chains distant

Give any further facts which will aid in finding this

Corner again.