

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

U-23

Posted

~~Chippewa~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 28 5 p Mer.

Center 25 Corner common to Sections

and

Corner consists of a concrete post

State condition brass plate Excellent

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? Put in by W. Dept

C. B. [Signature]

Signature.

Forest Ranger


6-5-36

Date.

Title.

Corner again.  
 Find a cut out of W. corner  
 South  
 There need cut out  
 just S of street part of  
 gone to great looking on  
 W. corner etc

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the  
 side of \_\_\_\_\_  
 from which this corner bears \_\_\_\_\_  
 chains distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near corner.) 8-8027

T. 146 N R. 27 W Mer.