

N-1

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 29-30W 5th Mer.

Section Corner common to Sections

13, 24, 18, and 19



Corner consists of a in road (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N
R. 29W
S. 18

T146N
R. 30W
S. 13

T146N
R. 29W
S. 19

B.T.

B.T.

B.T.

Species Ash Aspen N. Pine

Diameter 15" 8" 25"

Bearing N14E N57W S30E

Distance 1.59 ch 1.26 ch 4.42 ch.

Do you believe this to be a genuine Land Office Corner? Y

If not, why?

Harold Hennes

(Signature)


March 31, 1937

(Date)

(Time)

THE BOARD OF NATIONAL FIREARMS CONTROL
OF THE UNITED STATES DEPARTMENT OF JUSTICE
WASHINGTON, D. C.

Location post, used as temp. ...
Corner again.
Give any further facts which will aid in finding the
chains distant.
from which this Corner bears
side of
feet
inches diameter, on the
Metal Location Poster is on a
yellow post



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146N R. 29-S0W 5th Mer.

Section Corner common to Sections
13, 24, 18, and 19

Corner consists of a in road (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

18	24	19	18
NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N R.29W S.18	T146N R.29W S.18	T146N R.29W S.19	
B.T.	B.T.	B.T.	

Species Ash Aspen N. Pine
 Diameter 20" 2" 28"
 Bearing N42E N57E S80E
 Distance 1.49 ch 1.25 ch 4.12 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Harold Hennes

(Signature)

March 31, 1937

(Date)

(Time)


Location post used as temp. sec. cor. Corner again.

Give any further facts which will aid in finding this chains distant.


from which this Corner bears N90W

side of post tree 6 inches diameter, on the south

Metal Location Poster is on a yellow post



(Make sketch of topography near Corner)

PostedSection Corners N.W. Cor. of Sec. 19 on Range lineT 146N. R 29W. Mer. 5thCorner is
a Hub in Center
of Road.Height Dia Marked

BEARING TREES

	<u>T. 146N. R. 30W.</u>	<u>S. 29</u>	<u>T. 146N. R. 29W.</u>	<u>S. 19</u>
Marks	<u>BT</u>	<u>BT</u>	<u>BT</u>	<u> </u>
Species	<u>Aspen</u>	<u>W. Ash</u>	<u>N. Pine</u>	<u>W. Oak</u>
Diameter	<u>9"</u>	<u>6"</u>	<u>16"</u>	<u>14"</u>
Bearing	<u>N. 61° W.</u>	<u>S. 37° W.</u>	<u>S. 01° E.</u>	<u>N. 14° E.</u>
Lks Dist ^{ances}	<u>122</u>	<u>73½</u>	<u>445</u>	<u>151</u>

Metal poster on Remarks: Va. used 7°Date 6/4/34 Signed J. A. Gjelhaug

