

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5th P. Mer.

1/4 Corner common to Sections
20, and 21

Corner consists of a Brass cap on iron pipe in place

State condition Good

Dimensions above ground 7 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u> <u>cor.</u> <u>520/521</u>			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>cor.</u> <u>520/521</u>		<u>1/4 cor.</u> <u>520/521</u>	
<u>BT</u>		<u>BT</u>	

Species Maple E/m

Diameter 12" 16"

Bearing S19°W N27°E

Distance .27 chs. .41 chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Paul Moeller

(Signature)

11/29/28
(Date)

Tr. Forester P-1
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

two inches diameter, on the

Metal Location Poster is on a

	Geo.		Geo.
	Geo.		Geo.

(Make sketch of topography near corner)