

M-11

Form 874-9—Revised May, 1918

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5th Mer.

CS 1/16 Corner common to sections
NE/SW, SE/SW, NW/SE and SW/SE forties

Corner consists of a Square of State (not) in place



State condition good

Dimensions above ground 41 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____ No bear

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by FS survey

Paul Moller

(Signature)

Junior Forester

(Title)

Jan. 1939

(Date)

M-11

Corner again.

Give any further facts which will aid in finding this

chains distant.

62

from which this Corner bears


N 11° E

side of

tree 9 inches diameter, on the

slouch

Metal Location Post is on a 2' *Aspen*



(Sketch of topography near Corner)

T. 146N R. 29W

525 Mer. 10-11