

A-13  
On map

U. S. Department of Agriculture

FOREST SERVICE

Chippewa Trusted  
NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 N R. 29 W 5 20 Mer.

Section Corner common to Sections  
3/4 T 146 N R 29 W, and 33 + 34 T 147 N  
R 29 W

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 146 N  
R 29 W  
Sec 7

Sec  
34

\_\_\_\_\_

\_\_\_\_\_

BT

BT

\_\_\_\_\_

\_\_\_\_\_

Dead Species Basswood Basswood

Diameter 15" 8"

Bearing ✓ ✓

Distance ✓ ✓

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Bearing trees are original

A F Queller  
(Signature)

10/10/32  
(Date)

Asst Supervisor  
(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

(Make sketch of topography near Corner)