

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *146* / *149* R. *29* Mer.

Corner common to Sections *35*, *36*, *1*, and *2*

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *T. ...*
Diameter *5*
Bearing *No on ground*
Distance *1*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Survey more recent
Probably for SA surveying*


[Signature]
Signature

2-8-29
Date

FR
Title

(Make sketch of topography near corner.)

T. 146 R. 29 S. Mer. A-21



Metal Location Poster is on a *Tom*

tree 5 inches diameter, on the *SW*

side of *the*

from which this Corner bears *S 55 W*

18 feet chains distant.

Give any further facts which will aid in finding this

Corner again.

Monday June 30 1887
Corner was in ground
Corner was in ground
Corner was in ground